# Oil Field Environmental Incident Summary

Responsible Party: Enable Midstream Partners

Well Operator: XTO ENERGY INC.
Well Name: JOHNSRUD FEDERAL 34X-14

Field Name: BEAR DEN Well File #: 19273

Date Incident:4/20/2016Time Incident:22:13Facility ID Number:County:MCKENZIETwp:149Rng:96Sec:14Qtr:

Location Description: LAT: 47.71816 LONG: -102.92983 Enable owned and operated LACT Unit

located on the XTO well pad.

Submitted By: John Launius Received By:

Contact Person: John Launius

211 North Robinson Avenue

Suite 150

Oklahoma City, OK 73102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:2.9 MileDistance Nearest Water Well:2.9 Mile

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 5 Barrels 4.5 Barrels 4.5 barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 5/6/2016 Clean Up Concluded: 4/26/2016

## Risk Evaluation:

Low risk evaluation. Pooled liquids were recovered by vac truck. Released liquids were contained on site. Impact area was small.

## Areal Extent:

15 feet by 8 feet by 2 -12 inches in depth

## Potential Environmental Impacts:

Low to no environmental impacts. Soil impact depth is 12 inches or less.

## Action Taken or Planned:

Approximately 1 BBLs was released outside of the LACT unit onto the ground. All of the liquid was contained on site. The leak occurred at a Pulsation Damper valve (nipple failure) inside the LACT Unit building. Approximately 4 BBLs of produce water was contained inside the LACT Unit spill containment area. The Emergency Response contractor has responded to the incident and all free standing liquids on the ground and inside the LACT Unit containment area have been recovered. The recovered materials were transported off site to be disposed of properly. Additional remediation will be necessary. Impact depth to the ground surface is estimated to be less than 12 inches. An emergency one call notification has been issued. Due to underground utilities in the impacted area no excavation will occur until the one call has been cleared. Excavation & pad restoration work should begin on 4/22/2016 (estimated time necessary for one call process to be complete). Our environmental response contractor will provide cleanup services as directed. The contaminated soil will be excavated and placed in roll off containers. Further environmental actions include profile and disposal of the recovered material in an approved landfill.

Wastes Disposal Location: SECURE ENERGY SERVICES

3905 109th AVE NW Keene ND 58847

Agencies Involved:

**Updates** 

Date: 4/22/2016 Status: Reviewed - Follow-up Required Author: Souder, Taylor

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the report, the release was not contained. Further follow-up needed.

Date: 5/4/2016 Status: Inspection Author: Washek, Sandi

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

Arrived on site at 9:00 a.m. Weather was sunny with wind out of the SW at 10 mph. Temperature was 66 degrees F. The pad and area were under remediation work at the time of the inspection. There was a yellow pack-over bin located on the pad. There also was a large workover crew on an adjoining pad site. The liquids came out of the Lease Automatic Custody Transfer (LACT) containment area, but they did not leave the pad site. Some of the liquid soaked into the ground on the pad.

Date: 6/13/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

This release remained on location and should have been assigned to the NDIC. It is now transferred over to the NDIC.